SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch

EVALUATION REPORT

Repot No.	HZCPCHE23000148_EN
Sample name	ZIIP Beauty HALO
Client name	CBT AT-HOME BEAUTY HOLDINGS PTE. LTD.

2023-11-01

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

STATEMENT

1. This report will be invalid once altered, added or deleted.
2. The results shown in this evaluation report refer only to the information and/or sample received.
3. The evaluation is based on the information and/or sample provided by the client, and the client shall be responsible for the authenticity of the information and/or sample.
4. The results can not be used for false or exaggerated improper publicity.
5. SGS is not a clinical testing institution for medical devices and does not have the qualification to carry out clinical testing of medical devices in China. Considering the update of laws and regulations, such products may be classified as medical devices in China. SGS is not responsible for distinguishing such information. The applicant shall pay close attention to and identify whether such products are classified as medical devices in China. If the product is considered as medical devices, the applicant shall perform relevant obligations in accordance with the requirements of

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

the Regulations on the Supervision and Administration of Medical Devices.

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Evaluation Report **No: HZCPCHE23000148_EN draft** **Date: Nov 01 2023**

Client name: CBT AT-HOME BEAUTY HOLDINGS PTE. LTD.
Client address: 20 UPPER CIRCULAR ROAD #03-06 THE RIVERWALK SINGAPORE

Sample name: ZIIP Beauty HALO
Manufacturer: ZIIP
Manufacturer Address: 920 Country Club Drive Suite 1A, Moraga, CA 94556 USA

Above sample(s) was/were submitted and certified by the client, SGS quoted the information with no responsibility as to the accuracy, adequacy and/or completeness.

SGS job No.: HZCPCHE23000148-01
SGS reference No.: SHCPCHE23000183-01
Date of receipt: 2023-07-24
Evaluation Period: 2023-07-26~2023-09-06

Evaluation Requested:
Selected item(s) as requested by applicant:

Evaluation Method:
Protocol scheme with both signed

Evaluation Result/Conclusion:
Over the course of 42 days by 31 healthy male and female subjects, the test result showed that, the test product had firming, anti-wrinkle, spot-removing and whitening efficacy.

Remark:
This evaluation report is in Chinese and maybe translated into other languages, The Chinese version shall prevail.

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co.,Ltd Hangzhou Branch

.....
Authorized Signature Amy Fang

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Contents

1. Summary 6
2. Test Parameter 16
2.1. Image capture 16
2.2. Skin gloss 16
2.3. Skin elasticity 16
2.4. Skin firmness 16
2.5. Expert evaluation 16
2.6. Self-assessment 16
3. Inclusion and Exclusion Criteria 17
3.1. Inclusion criteria 17
3.2. Exclusion criteria 17
4. Test Result 19
4.1. Skin tone (VISIA CR-IPP) (Cheek) 19
4.2. Skin evenness (VISIA CR-IPP) (Cheek) 23
4.3. Skin wrinkles (Primos-CR) (Forehead) 25
4.4. Skin wrinkles (Primos-CR) (Crow's feet) 33
4.5. Skin wrinkles (Primos-CR) (Nasolabial fold) 41
4.6. Skin gloss (Glossymeter® GL200) (Cheek) 49
4.7. Skin elasticity (Cutometer® dual MPA580) (Cheek) 51
4.8. Skin firmness F4 (Cutometer® dual MPA580) (Cheek) 56
4.9. Expert evaluation 58
4.10. Self-assessment 59
5. Conclusion 62
6. Adverse Events 62
7. Deviations and revisions to the protocol 62
8. Sample Photo 63
9. Appendix I: Subject Information 64
10. Appendix II: Protocol 66
11. Appendix III: Image capture of part of subjects 76

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

1. Summary

Test Sample: ZIIP BEAUTY HALO

Test Objective: This single-center clinical trial is being conducted to assess the rate of improvement in terms of skin elasticity, skin firmness, skin gloss, skin evenness, degree of pigmentation, and degree of wrinkles of the Sponsor's test sample when used over the course of 42 day by healthy adults.

Test Method: Protocol scheme with both signed.

Subject: Total 31 healthy Asian males and females completed the test (including 2 males and 29 females), aged from 35 to 55 years old, mean age 47.87±5.15 and all met the inclusion and exclusion criteria.

Test Position: Face

Usage Method: Step 1: Charging

When the instrument needs to be charged, the light band around the center of the instrument will flash orange.

To charge, plug the charger into the USB power adapter (not supplied with this product) and then plug the other end into the terminal port of the HALO instrument. The light band will show orange color when charging. It takes 4 hours to fully charge the instrument. When charging is complete, the orange light band will turn off.

WARNING: Do not attempt to use the instrument while charging. The product must be charged with an adapter that complies with the GB4706.1-2005 standard and has an output power of less than 15W.

Step 2: Skin Preparation

Before use, make sure your skin is dry, clean and free of any skincare products such as moisturizers, serums or lotions. Ensure that you are not wearing any jewelry in the area where the device is used or on your hands.

If you have used an oil-based cleanser, make sure there is no residue on your skin as this can cause HALO not to work.

Those with facial hair should shave their face before use. Hair can interfere with the electrical conductivity of the spheres, causing the device to not work.

Step 3: Apply the gel, hold down the switch and start using it according to the video's technique. At the end of use, use it again, if the gel is not enough you need to replenish the gel. Stop after two times consecutive uses.

Wipe off any remaining gel on the skin. Toner or moisturizer can be used immediately as needed. Ensure the device is clean and dry before storing.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 化妆品及日化产品部 Cosmetics, Personal Care & Household
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

The use cycle is continuous two days, one day of rest, and two days of use. Use the 4-minute mode twice a day in a row for a total of 8 minutes.

Application Period: 42 days

Test Period: Before application (D0), Immediately after application (D0Timm), 7 days after application (D7), 21 days after application (D21), 42 days after application (D42)

Test parameters: 1. Take image with VISIA CR. Analyze the skin evenness, skin tone by IPP.

2. Take image capture with Primos CR and analyze skin wrinkles
3. The skin gloss is determined by the Glossymeter® GL200.
4. Measurement of skin elasticity and skin firmness with Cutometer® dual MPA580.
5. Expert assessment
6. Subject self-assessment

Study Design:

Before application (D0)

After the subjects arrived at SGS, they would use facial cleanser provided by the laboratory to clean the face, dried the skin with a lint free dry paper tissue, and sat quietly for 30 minutes in the clinic at a temperature of 21±2℃ and 50±10% RH

The expert conducted the assessment.

The technician captured facial VISIA CR images and Primos CR images for qualified subjects and conducted the Cutometer measurement and Glossymeter measurement.

The subjects filled in the self-assessment questionnaire.

The technician explained the product instructions to the subjects and distributed the test samples. If there are adverse reactions, they need to fill in the use log in time.

Immediately after application (D0Timm)

Subjects used facial cleanser provided by the laboratory to clean the face, dry the skin with a lint free dry paper tissue, and sat quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.

The technician conducted the Cutometer measurement.

Subjects left SGS.

7 days after application (D7)

After the subjects arrived at SGS, they would use facial cleanser provided by the laboratory to clean the face, dried the skin with a lint free dry paper tissue, and sat quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

The dermatologist conducted the assessment.

The technician captured facial VISIA CR images, Primos CR images for qualified subjects and conducts the Cutometer measurement and Glossymeter measurement.

The subjects filled in the self-assessment questionnaire.

The technician weighted the test samples and checked the product usage log.

Subjects left SGS.

21 days after application (D21)

After the subjects arrived at SGS, they would use facial cleanser provided by the laboratory to clean the face, dried the skin with a lint free dry paper tissue, and sat quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.

The dermatologist conducted the assessment.

The technician captured facial VISIA CR images, Primos CR images for qualified subjects and conducts the Cutometer measurement and Glossymeter measurement.

The subjects filled in the self-assessment questionnaire.

The technician weighted the test samples and the product usage log.

Subjects left SGS.

42 days after application (D42)

After the subjects arrived at SGS, they would use facial cleanser provided by the laboratory to clean the face, dried the skin with a lint free dry paper tissue, and sat quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.

The dermatologist conducted the assessment.

The technician captured facial VISIA CR images, Primos CR images for qualified subjects and conducts the Cutometer measurement and Glossymeter measurement.

The subjects filled in the self-assessment questionnaire.

The technician recycled the test samples and the product usage log.

Subjects left SGS.

Statistical Analysis: SPSS 28.0 is used for data statistics, and the test data are tested for normal distribution. If the test data are normally distributed, the T-test method is used for statistical analysis; if the test data are non-normal distribution, the rank sum test method is used for statistical analysis. The rank data is statistically analyzed by the rank sum test. Statistical methods significance level $P<0.05$

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Test Results:

1) Equipment measurement

Parameter (Equipment) (Site)	Time point	Rate of change	Significant *P* value compared with D0	Improved subjects (Percentage of improved subjects)	Remarks
Skin tone L* (VISIA CR-IPP) (Cheek)	D7	0.12%	Non-significantly	15（48%）	The higher the analysis value, the brighter the skin color.
	D21	0.11%	Non-significantly	19（61%）	
	D42	1.52%	**Significantly**	28（90%）	
Skin tone ITA° (VISIA CR-IPP) (Cheek)	D7	-0.26%	Non-significantly	15（48%）	The higher the analysis value, the lighter the skin color.
	D21	-2.05%	Non-significantly	13（42%）	
	D42	4.78%	**Significantly**	28（90%）	
Intensity-SD (VISIA CR-IPP) (Cheek)	D7	-4.97%	**Significantly**	26（84%）	The lower the analysis value, the better the skin evenness.
	D21	-6.89%	**Significantly**	24（77%）	
	D42	-10.91%	**Significantly**	31（100%）	
Average depth of wrinkles (Primos-CR) (Forehead)	D7	-7.23%	**Significantly**	21（68%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-7.38%	**Significantly**	18（58%）	
	D42	-6.81%	Non-significantly	15（48%）	
Number of wrinkles (Primos-CR) (Forehead)	D7	0.00%	Non-significantly	0（0%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-1.08%	Non-significantly	1（3%）	
	D42	-1.08%	Non-significantly	1（3%）	
Volume of wrinkles (Primos-CR) (Forehead)	D7	-21.72%	**Significantly**	28（90%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-24.06%	**Significantly**	24（77%）	
	D42	-27.53%	**Significantly**	30（97%）	
Area of wrinkles (Primos-CR) (Forehead)	D7	-14.29%	**Significantly**	27（87%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-15.95%	**Significantly**	28（90%）	
	D42	-19.69%	**Significantly**	29（94%）	
Length of wrinkles (Primos-CR) (Forehead)	D7	-4.78%	**Significantly**	21（68%）	The analyzed value lower, the skin wrinkle had
	D21	-5.58%	Non-significantly	16（52%）	

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Parameter (Equipment) (Site)	Time point	Rate of change	Significant *P* value compared with D0	Improved subjects (Percentage of improved subjects)	Remarks
	D42	-5.38%	Non-significantly	18（58%）	been improved
Average depth of wrinkles (Primos-CR) (Crow's feet)	D7	-3.68%	Non-significantly	22（71%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-4.83%	**Significantly**	17（55%）	
	D42	-2.41%	Non-significantly	16（52%）	
Number of wrinkles (Primos-CR) (Crow's feet)	D7	-2.15%	Non-significantly	2（6%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-3.23%	Non-significantly	3（10%）	
	D42	-6.45%	Non-significantly	5（16%）	
Volume of wrinkles (Primos-CR) (Crow's feet)	D7	-12.23%	**Significantly**	26（84%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-16.33%	**Significantly**	24（77%）	
	D42	-19.93%	**Significantly**	26（84%）	
Area of wrinkles (Primos-CR) (Crow's feet)	D7	-11.05%	**Significantly**	27（87%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-11.26%	**Significantly**	25（81%）	
	D42	-17.92%	**Significantly**	31（100%）	
Length of wrinkles (Primos-CR) (Crow's feet)	D7	-0.71%	Non-significantly	11（35%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-1.19%	Non-significantly	10（32%）	
	D42	-5.95%	Non-significantly	15（48%）	
Average depth of wrinkles (Primos-CR) (Nasolabial fold)	D7	-3.15%	**Significantly**	20（65%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-3.71%	Non-significantly	15（48%）	
	D42	-2.89%	Non-significantly	15（48%）	
Number of wrinkles (Primos-CR) (Nasolabial fold)	D7	0.00%	Non-significantly	0（0%）	The analyzed value lower, the skin wrinkle had been improved
	D21	0.00%	Non-significantly	0（0%）	
	D42	0.00%	Non-significantly	0（0%）	
Volume of wrinkles (Primos-CR) (Nasolabial fold)	D7	-10.86%	**Significantly**	23（74%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-14.73%	**Significantly**	24（77%）	
	D42	-15.62%	**Significantly**	26（84%）	

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国・浙江・杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Parameter (Equipment) (Site)	Time point	Rate of change	Significant *P* value compared with D0	Improved subjects (Percentage of improved subjects)	Remarks
Area of wrinkles (Primos-CR) (Nasolabial fold)	D7	-6.81%	**Significantly**	22（71%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-11.61%	**Significantly**	24（77%）	
	D42	-13.07%	**Significantly**	27（87%）	
Length of wrinkles (Primos-CR) (Nasolabial fold)	D7	-9.58%	**Significantly**	19（61%）	The analyzed value lower, the skin wrinkle had been improved
	D21	-6.01%	Non-significantly	15（48%）	
	D42	-11.36%	**Significantly**	21（68%）	
Skin gloss （Glossymeter® GL200（Cheek）	D7	2.36%	**Significantly**	31（100%）	The higher the test value, the better the skin gloss
	D21	5.48%	**Significantly**	31（100%）	
	D42	10.07%	**Significantly**	31（100%）	
Skin elasticity R2 (Cutometer® dual MPA580) (Cheek)	D0Timm	7.51%	**Significantly**	31（100%）	The higher the test value, the better the skin elasticity.
	D7	5.59%	**Significantly**	30（97%）	
	D21	8.96%	**Significantly**	30（97%）	
	D42	13.46%	**Significantly**	31（100%）	
Skin elasticity R5 (Cutometer® dual MPA580) (Cheek)	D0Timm	9.27%	**Significantly**	26（84%）	The higher the test value, the better the skin elasticity.
	D7	9.69%	**Significantly**	29（94%）	
	D21	12.93%	**Significantly**	30（97%）	
	D42	19.74%	**Significantly**	31（100%）	
Skin elasticity R7 (Cutometer® dual MPA580) (Cheek)	D0Timm	13.14%	**Significantly**	27（87%）	The higher the test value, the better the skin elasticity.
	D7	14.36%	**Significantly**	30（97%）	
	D21	20.51%	**Significantly**	31（100%）	
	D42	26.72%	**Significantly**	31（100%）	
Skin elasticity F4 (Cutometer® dual MPA580) (Cheek)	D0Timm	-12.17%	**Significantly**	30（97%）	The lower the test value, the better the skin firmness.
	D7	-9.39%	**Significantly**	30（97%）	
	D21	-16.41%	**Significantly**	31（100%）	
	D42	-23.70%	**Significantly**	31（100%）	

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国・浙江・杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

2) Expert evaluation (Skin condition)

Item	Time point	Rate of Change	Significant *P* value compared with D0	Remarks
Facial skin gloss	D7	-1.66%	Non-significantly	The lower the score, the skin gloss had been improved
	D21	-3.97%	**Significantly**	
	D42	-8.94%	**Significantly**	
Facial skin evenness	D7	-0.66%	Non-significantly	The lower the score, the skin evenness had been improved
	D21	-3.30%	**Significantly**	
	D42	-7.92%	**Significantly**	
Forehead wrinkles	D7	-1.42%	Non-significantly	The lower the score, the wrinkles had been improved
	D21	-2.36%	Non-significantly	
	D42	-5.66%	**Significantly**	
Nasolabial fold wrinkles	D7	-1.20%	Non-significantly	The lower the score, the wrinkles had been improved
	D21	-2.00%	Non-significantly	
	D42	-5.60%	**Significantly**	
Crow's feet wrinkles	D7	-1.81%	Non-significantly	The lower the score, the wrinkles had been improved
	D21	-3.17%	**Significantly**	
	D42	-7.69%	**Significantly**	
Color difference between the isolated hyperpigmentation and the surrounding skin	D7	-1.38%	Non-significantly	The lower the score, the small color difference is.
	D21	-2.76%	Non-significantly	
	D42	-13.79%	**Significantly**	

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

3) Self-assessment (Skin condition)

Item	Time point	Change value	Significant *P* value compared with D0	Remarks
Skin firmness	D7	-1.10	**Significantly**	Evaluation standard: 0 to 9 score (0 score means very good; 4-5 score means general; 9 score means very poor).
	D21	-2.45	**Significantly**	
	D42	-3.58	**Significantly**	
Skin gloss	D7	-1.16	**Significantly**	
	D21	-2.48	**Significantly**	
	D42	-3.77	**Significantly**	
Skin hyperpigmentation	D7	-1.32	**Significantly**	
	D21	-2.58	**Significantly**	
	D42	-3.81	**Significantly**	
Forehead wrinkles	D7	-1.26	**Significantly**	
	D21	-2.65	**Significantly**	
	D42	-3.81	**Significantly**	
Crow's feet wrinkles	D7	-1.10	**Significantly**	
	D21	-2.42	**Significantly**	
	D42	-3.42	**Significantly**	
Nasolabial folds	D7	-1.19	**Significantly**	
	D21	-2.55	**Significantly**	
	D42	-3.81	**Significantly**	
Skin evenness	D7	-1.26	**Significantly**	
	D21	-2.77	**Significantly**	
	D42	-3.97	**Significantly**	
Jawline lifting	D7	-1.23	**Significantly**	
	D21	-2.71	**Significantly**	
	D42	-3.94	**Significantly**	
Skin hydration	D7	-1.06	**Significantly**	

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Item	Time point	Change value	Significant *P* value compared with D0	Remarks
	D21	-2.39	**Significantly**	
	D42	-3.52	**Significantly**	

4) Self-assessment (Satisfaction)

7 days after application, 90% subjects thought "After using, felling the product is mild and non-irritating", 87% subjects thought "After using, felling the skin is more elastic", 90% subjects thought "After using, the skin touches smoother ", 87% subjects thought "After using, the product is effective in improving dullness of the skin", 84% subjects thought "After using, feeling the skin is more translucent", 90% subjects thought "After using, the product is effective in firming the skin", 87% subjects thought "After using, the product is effective in minimizing dry fine lines", 84% subjects thought "After using, the product is effective in improving sagging", 87% subjects thought "After using, the product is effective in improving skin roughness", 87% subjects thought "After using, the product is effective in enhancing the skin's gloss", 87% subjects thought "After using, satisfied with product effect/efficacy", 87% subjects thought "After using, willing continue using the product", 90% subjects thought "After using, would recommend the product to friends", 81% subjects thought "After using, thinking the skin is fairer", 81% subjects thought "After using, thinking the skin is more delicate ", 90% subjects thought "Easy to use", 87% subjects thought "After using, the product is effective in immediate lifting and firming ", 87% subjects thought "After using, the lifting and firming effect lasts all day ", 87% subjects thought "The gel used with is easy to apply", 90% subjects thought "The gel used with is easy to clean", 87% subjects thought "After using, the product is effective in improving firmness of jawline".

21 days after application, 100% subjects thought "After using, felling the product is mild and non-irritating", 100% subjects thought "After using, felling the skin is more elastic", 100% subjects thought "After using, the skin touches smoother ", 100% subjects thought "After using, the product is effective in improving dullness of the skin", 100% subjects thought "After using, feeling the skin is more translucent", 100% subjects thought "After using, the product is effective in firming the skin", 100% subjects thought "After using, the product is effective in minimizing dry fine lines", 100% subjects thought "After using, the product is effective in improving sagging", 100% subjects thought "After using, the product is effective in improving skin roughness", 100% subjects thought "After using, the product is effective in enhancing the skin's gloss", 100% subjects thought "After using, satisfied with product effect/efficacy", 100% subjects thought "After using, willing continue using the product", 100% subjects thought "After using, would recommend the product to friends", 100% subjects thought "After using, thinking the skin is fairer", 100% subjects thought "After using, thinking the skin is more delicate ", 100% subjects thought "Easy to use", 100% subjects thought "After using, the product is effective in immediate lifting and firming ", 100% subjects thought "After using, the lifting and firming effect lasts all day ", 100% subjects thought "The gel used with is easy to apply", 100% subjects thought "The gel used with is easy to clean", 100% subjects thought "After using, the product is effective in improving firmness of jawline".

42 days after application, 97% subjects thought "After using, felling the product is mild and non-

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

irritating", 100% subjects thought "After using, felling the skin is more elastic", 97% subjects thought "After using, the skin touches smoother ", 97% subjects thought "After using, the product is effective in improving dullness of the skin", 97% subjects thought "After using, feeling the skin is more translucent", 100% subjects thought "After using, the product is effective in firming the skin", 97% subjects thought "After using, the product is effective in minimizing dry fine lines", 97% subjects thought "After using, the product is effective in improving sagging", 97% subjects thought "After using, the product is effective in improving skin roughness", 97% subjects thought "After using, the product is effective in enhancing the skin's gloss", 97% subjects thought "After using, satisfied with product effect/efficacy", 97% subjects thought "After using, willing continue using the product", 97% subjects thought "After using, would recommend the product to friends", 97% subjects thought "After using, thinking the skin is fairer", 97% subjects thought "After using, thinking the skin is more delicate ", 97% subjects thought "Easy to use", 97% subjects thought "After using, the product is effective in immediate lifting and firming ", 97% subjects thought "After using, the lifting and firming effect lasts all day ", 97% subjects thought "The gel used with is easy to apply", 97% subjects thought "The gel used with is easy to clean", 97% subjects thought "After using, the product is effective in improving firmness of jawline".

Conclusion:
Over the course of 42 days by 31 healthy male and female subjects, the test result showed that, the test product had firming, anti-wrinkle, spot-removing and whitening efficacy.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

2. Test Parameter

2.1. Image capture

Take image capture with VISIA CR and image analysis with Image-Pro skin comprehensive analysis software to analyze the skin evenness and skin tone. The lower the analysis value of Intensity-SD, the better the skin evenness. Analyze the skin tone with the image. The higher the skin tone L* value, the brighter the skin tone; the higher the skin tone ITA° value, the lighter the skin tone.

Take image capture with Primos. Analyze the skin wrinkle with the image, the analyzed value is lower means the skin wrinkle had improved.

2.2. Skin gloss

The skin gloss is determined by the Glossymeter® GL200. The higher the test value, the better the skin gloss.

2.3. Skin elasticity

The skin elasticity is determined by the Cutometer® MPA580. The higher the test value, the better the skin elasticity.

2.4. Skin firmness

The skin firmness is determined by the Cutometer® MPA580. The lower the test value, the better the skin firmness.

2.5. Expert evaluation

Experts evaluate the skin status of the subjects (facial skin gloss, facial skin evenness, forehead wrinkles, nasolabial fold wrinkles, crow's feet wrinkles, color difference between the isolated hyperpigmentation and the surrounding skin).

Grading scale：

（1） Facial skin gloss: 0-9 score (SGS standard grading scale)
（2） Facial skin evenness: 0-9 score (SGS standard grading scale)
（3） Forehead wrinkles: 0-9 score (SGS standard grading scale)
（4） Nasolabial fold wrinkles: 0-9 score (SGS standard grading scale)
（5） Crow's feet wrinkles: 0-9 score (SGS standard grading scale)
（6） Color difference between the isolated hyperpigmentation and the surrounding skin: 0-5 score (Skin Aging Atlas (Asian))

2.6. Self-assessment

Subjects conducted self-assessment according to their own use about skin condition, product efficacy and satisfaction.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

3. Inclusion and Exclusion Criteria

The subjects were selected from CPCH volunteer database. The following criteria were used for selection of subjects:

3.1. Inclusion criteria

- Healthy male or female, 25 to 55 years of age.
- Race: Asian (Chinese).
- Self-reported facial complexion is dull, rough and lacks elasticity.
- The tactile assessment of facial laxity 3-6.
- Facial hyperpigmentation ⩾ 3mm in diameter and the isolated hyperpigmentation has a visual score of 1-4 on the color difference between the hyperpigmentation and the surrounding skin, according to the Skin Aging Atlas (Asian).
- The forehead wrinkles on a visual scale of 2-6 (according to the SGS standard map).
- The nasolabial fold on random side of face on a visual scale of 3-6 (according to the SGS standard map).
- The crow's feet on random side of eyes on a visual scale of 3-6 (according to the SGS standard map).
- No obvious skin redness, lesions, scars, hair, etc. on the facial skin.
- Be able to cooperate well with the test according to the requirements of the test plan and maintain the regularity of life during the test period.

3.2. Exclusion criteria

Those with any of the following conditions must be excluded from this study:

- Those who do not agree to sign the informed consent form.
- Those who are unwilling to comply with the program requirements.
- Currently participating in any other clinical trial at the same time.
- Use of cosmetic products or/and medicines on the day of the test.
- Breastfeeding, pregnant, or planning to become pregnant during the study according to subject self-report.
- Currently receiving drug treatment during the test period.
- Those who are suffering from infectious skin diseases or atopic dermatitis.
- Those who with skin abnormalities such as moles and telangiectasia at the test sites.
- Those who have received skin peeling or skin treatment within 3 months before taking the test.
- Those who have received immunosuppressive therapy within 3 months before taking the test.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 通标标准技术服务有限公司杭州分公司 化妆品及日化产品部 Cosmetics, Personal Care & Household

7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- Those who have received systemic steroid therapy or phototherapy within 1 month before taking the test.
- Those who have used topical drugs or/and skin care products, cosmetics with special effects (claiming the effects of spot-removing and whitening, anti-wrinkles, firmness) on the involved parts within 2 weeks before participating in the test.
- There are obvious marks or other abnormalities in the test area, making it difficult to measure.
- Those who with severe reactions or allergies to cosmetics, drugs, or general light exposure.
- Those who are suspected or diagnosed predisposition to seizures during pregnancy.
- Those who are suspected or diagnosed heart disease.
- Those who are suffering from cancer/tumor.
- Those who with pacemakers, implantable defibrillators or other implanted metallic or electronic devices.
- In addition to the above, when it is deemed inappropriate to conduct the test according to the judgment of Investigator of the test.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

4. Test Result

4.1. Skin tone (VISIA CR-IPP) (Cheek)

The higher the skin tone L* value, the brighter the skin tone; the higher the skin tone ITA° value, the lighter the skin tone.




Fig.1.1 Skin tone L* value

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.1.2 Skin tone ITA° value

*Remarks: * means there's a significant difference compared with before application (p<0.050)*

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.1.3 Change value of skin tone L*




Fig.1.4 Change value of skin tone ITA°

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.1.5 Rate of change of skin tone L*

Rate of change = (test value after application - test value before application) ÷ test value before application × 100%




Fig.1.6 Rate of change of skin tone ITA°

Rate of change = (test value after application - test value before application) ÷ test value before application × 100%

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Compared with before application:
7 days after application, the skin tone L* increased by 0.12% non-significantly; the skin tone ITA° decreased by 0.26% non-significantly;

21 days after application, the skin tone L* increased by 0.11% non-significantly; the skin tone ITA° decreased by 2.05% non-significantly;

42 days after application, the skin tone L* increased by 1.52% significantly; the skin tone ITA° increased by 4.78% significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

4.2. Skin evenness (VISIA CR-IPP) (Cheek)

The lower the analysis value, the better the skin evenness.




Fig.2.1 Intensity-SD

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.2.2 Change value of Intensity-SD

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.2.3 Rate of change of Intensity-SD

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Compared with before application:
7 days after application, the Intensity-SD of cheek decreased by 4.97% significantly.
21 days after application, the Intensity-SD of cheek decreased by 6.89% significantly.
42 days after application, the Intensity-SD of cheek decreased by 10.91% significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

4.3. Skin wrinkles (Primos-CR) (Forehead)

The analyzed value lower, the skin wrinkle had improved.




Fig.3.1 Number of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.3.2 Volume of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 浙标标准技术服务有限公司杭州分公司 化妆品及日化产品部 Cosmetics, Personal Care & Household

7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.3.3 Area of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.3.4 Length of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.3.5 Average depth of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.3.6 Change value of number of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.3.7 Change value of volume of wrinkles




Fig.3.8 Change value of area of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.3.9 Change value of length of wrinkles




Fig.3.10 Change value of average depth of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.3.11 Rate of change of number of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%




Fig.3.12 Rate of change of volume of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.3.13 Rate of change of area of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%




Fig.3.14 Rate of change of length of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.3.15 Rate of change of average depth of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Compared with before application:

7 days after application, number of wrinkles of test area of forehead had no change, volume of wrinkles of test area decreased by 21.72% significantly, area of wrinkles of test area decreased by 14.29% significantly, length of wrinkles of test area decreased by 4.78% significantly, average depth of wrinkles of test area decreased by 7.23% significantly.

21 days after application, number of wrinkles of test area of forehead decreased by 1.08% non-significantly, volume of wrinkles of test area decreased by 24.06% significantly, area of wrinkles of test area decreased by 15.95% significantly, length of wrinkles of test area decreased by 5.58% non-significantly, average depth of wrinkles of test area decreased by 7.38% significantly.

42 days after application, number of wrinkles of test area of forehead decreased by 1.08% non-significantly, volume of wrinkles of test area decreased by 27.53% significantly, area of wrinkles of test area decreased by 19.69% significantly, length of wrinkles of test area decreased by 5.38% non-significantly, average depth of wrinkles of test area decreased by 6.81% non-significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

4.4. Skin wrinkles (Primos-CR) (Crow's feet)

The analyzed value lower, the skin wrinkle had improved.




Fig.4.1 Number of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.4.2 Volume of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.4.3 Area of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.4.4 Length of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.4.5 Average depth of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.4.6 Change value of number of wrinkles

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 浙标标准技术服务有限公司杭州分公司 化妆品及日化产品部 Cosmetics, Personal Care & Household

7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.4.7 Change value of volume of wrinkles




Fig.4.8 Change value of area of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.4.9 Change value of length of wrinkles




Fig.4.10 Change value of average depth of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.4.11 Rate of change of number of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%




Fig.4.12 Rate of change of volume of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.4.13 Rate of change of area of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%




Fig.4.14 Rate of change of length of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.4.15 Rate of change of average depth of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Compared with before application:

7 days after application, number of wrinkles of test area of crow's feet decreased by 2.15% non-significantly, volume of wrinkles of test area decreased by 12.23% significantly, area of wrinkles of test area decreased by 11.05% significantly, length of wrinkles of test area decreased by 0.71% non-significantly, average depth of wrinkles of test area decreased by 3.68% non-significantly.

21 days after application, number of wrinkles of test area of crow's feet decreased by3.23% non-significantly, volume of wrinkles of test area decreased by 16.33% significantly, area of wrinkles of test area decreased by 11.26% significantly, length of wrinkles of test area decreased by 1.19% non-significantly, average depth of wrinkles of test area decreased by 4.83% significantly.

42 days after application, number of wrinkles of test area of crow's feet decreased by 6.45% non-significantly, volume of wrinkles of test area decreased by 19.93% significantly, area of wrinkles of test area decreased by 17.92% significantly, length of wrinkles of test area decreased by 5.95% non-significantly, average depth of wrinkles of test area decreased by 2.41% non-significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

4.5. Skin wrinkles (Primos-CR) (Nasolabial fold)

The analyzed value lower, the skin wrinkle had improved.




Fig.5.1 Number of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.5.2 Volume of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.5.3 Area of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.5.4 Length of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.5.5 Average depth of wrinkles

*Remarks: * means there's a significant difference compared with before application (p<0.050)*




Fig.5.6 Change value of number of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.5.7 Change value of volume of wrinkles




Fig.5.8 Change value of area of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.5.9 Change value of length of wrinkles




Fig.5.10 Change value of average depth of wrinkles

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.5.11 Rate of change of number of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%




Fig.5.12 Rate of change of volume of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.5.13 Rate of change of area of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%




Fig.5.14 Rate of change of length of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.5.15 Rate of change of average depth of wrinkles

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Compared with before application:

7 days after application, number of wrinkles of test area of nasolabial fold had no change, volume of wrinkles of test area decreased by 10.86% significantly, area of wrinkles of test area decreased by 6.81% significantly, length of wrinkles of test area decreased by 9.58% significantly, average depth of wrinkles of test area decreased by 3.15% significantly.

21 days after application, number of wrinkles of test area of nasolabial fold had no change, volume of wrinkles of test area decreased by 14.73% significantly, area of wrinkles of test area decreased by 11.61% significantly, length of wrinkles of test area decreased by 6.01% non-significantly, average depth of wrinkles of test area decreased by 3.71% non-significantly.

42 days after application, number of wrinkles of test area of nasolabial fold had no change, volume of wrinkles of test area decreased by 15.62% significantly, area of wrinkles of test area decreased by 13.07% significantly, length of wrinkles of test area decreased by 11.36% significantly, average depth of wrinkles of test area decreased by 2.89% non-significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

4.6. Skin gloss (Glossymeter® GL200) (Cheek)

The higher the analysis value, the better the skin gloss.




Fig.6.1 Skin gloss

*Remarks: * means there's a significant difference compared with before application (P<0.05)*




Fig.6.2 Change value of skin gloss

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.6.3 Rate of change of skin gloss

Rate of change = (analysis value after application - analysis value before application) ÷ analysis value before application × 100%

Compared with before application:
7 days after application, the skin gloss of cheek increased by 2.36% significantly.
21 days after application, the skin gloss of cheek increased by 5.48% significantly.
42 days after application, the skin gloss of cheek increased by 10.07% significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

4.7. Skin elasticity (Cutometer® dual MPA580) (Cheek)

The larger the measured value, the better the skin elasticity.




Fig.7.1 Skin elasticity R2

*Remarks: * means there's a significant difference compared with baseline (p<0.05)*




Fig.7.2 Skin elasticity R5

*Remarks: * means there's a significant difference compared with baseline (p<0.05)*

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.7.3 Skin elasticity R7

*Remarks: * means there's a significant difference compared with baseline (p<0.05)*




Fig.7.4 Change of skin elasticity R2

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 化妆品及日化产品部 Cosmetics, Personal Care & Household

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.7.5 Change of skin elasticity R5




Fig.7.6 Change of skin elasticity R7

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.7.7 Rate of change of skin elasticity R2

Rate of change = (test value after application - test value before application) ÷ test value before application × 100%




Fig.7.8 Rate of change of skin elasticity R5

Rate of change = (test value after application - test value before application) ÷ test value before application × 100%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)




Fig.7.9 Rate of change of skin elasticity R7

Rate of change = (test value after application - test value before application) ÷ test value before application × 100%

Compared with before application:

Immediately after application, the skin elasticity R2 of cheek increased by 7.51% significantly, the skin elasticity R5 of cheek increased by 9.27% significantly, the skin elasticity R7 of cheek increased by 13.14% significantly.

7 days after application, the skin elasticity R2 of cheek increased by 5.59% significantly, the skin elasticity R5 of cheek increased by 9.69% significantly, the skin elasticity R7 of cheek increased by 14.36% significantly.

21 days after application, the skin elasticity R2 of cheek increased by 8.96% significantly, the skin elasticity R5 of cheek increased by 12.93% significantly, the skin elasticity R7 of cheek increased by 20.51% significantly.

42 days after application, the skin elasticity R2 of cheek increased by 13.46% significantly, the skin elasticity R5 of cheek increased by 19.74% significantly, the skin elasticity R7 of cheek increased by 26.72% significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

4.8. Skin firmness F4 (Cutometer® dual MPA580) (Cheek)

The lower the test value, the better the skin firmness.




Fig.8.1 Skin firmness F4

*Remarks: * means there's a significant difference compared with baseline (p<0.05)*




Fig.8.2 Change of skin firmness F4

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)




Fig.8.3 Rate of change of skin firmness F4

Rate of change = (test value after application - test value before application) ÷ test value before application × 100%

Compared with before application:

Immediately after application, the skin firmness F4 of cheek decreased by 12.17% significantly.

7 days after application, the skin firmness F4 of cheek decreased by 9.39% significantly.

21 days after application, the skin firmness F4 of cheek decreased by 16.41% significantly.

42 days after application, the skin firmness F4 of cheek decreased by 23.70% significantly.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

4.9. Expert evaluation

Table 1 Result of expert evaluation (Skin condition)

Item	Mean				Rate of change			Significant *P* value compared with D0		
	D0	D7	D21	D42	D7	D21	D42	D7	D21	D42
Facial skin gloss	4.87	4.79	4.68	4.44	-1.66%	-3.97%	-8.94%	0.063	<0.001	<0.001
Facial skin evenness	4.89	4.85	4.73	4.50	-0.66%	-3.30%	-7.92%	0.500	0.002	<0.001
Forehead wrinkles	3.42	3.37	3.34	3.23	-1.42%	-2.36%	-5.66%	0.250	0.063	0.001
Nasolabial fold wrinkles	4.03	3.98	3.95	3.81	-1.20%	-2.00%	-5.60%	0.250	0.063	<0.001
Crow's feet wrinkles	3.56	3.50	3.45	3.29	-1.81%	-3.17%	-7.69%	0.125	0.016	<0.001
Color difference between the isolated hyperpigmentation and the surrounding skin	2.34	2.31	2.27	2.02	-1.38%	-2.76%	-13.79%	0.500	0.125	<0.001

Grading scale:（1） Facial skin gloss: 0-9 score (SGS standard grading scale)

（2） Facial skin evenness: 0-9 score (SGS standard grading scale)

（3） Forehead wrinkles: 0-9 score (SGS standard grading scale)

（4） Nasolabial fold wrinkles: 0-9 score (SGS standard grading scale)

（5） Crow' s feet wrinkles: 0-9 score (SGS standard grading scale)

（6） Color difference between the isolated hyperpigmentation and the surrounding skin: 0-5 score (Skin Aging Atlas (Asian))

Compared with before application:

7 days after application, the score of facial skin gloss decreased by 1.66% non-significantly, the score of facial skin evenness decreased by 0.66% non-significantly, the score of forehead wrinkles decreased by 1.42% non-significantly, the score of nasolabial fold wrinkles decreased by 1.20% non-significantly, the score of crow's feet wrinkles decreased by 1.81% non-significantly, the score of color difference between the isolated hyperpigmentation and the surrounding skin decreased by 1.38% non-significantly.

21 days after application, the score of facial skin gloss decreased by 3.97% significantly, the score of facial skin evenness decreased by 3.30% significantly, the score of forehead wrinkles decreased by 2.36% non-significantly, the score of nasolabial fold wrinkles decreased by 2.00% non-significantly, the score of crow's feet wrinkles decreased by 3.17% significantly, the score of color difference between the isolated hyperpigmentation and the surrounding skin decreased by 2.76% non-significantly.

42 days after application, the score of facial skin gloss decreased by 8.94% significantly, the score of facial skin evenness decreased by 7.92% significantly, the score of forehead wrinkles decreased by 5.66% significantly, the score of nasolabial fold wrinkles decreased by 5.60% significantly, the score

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

of crow's feet wrinkles decreased by 7.69% significantly, the score of color difference between the isolated hyperpigmentation and the surrounding skin decreased by 13.79% significantly.

4.10. Self-assessment

Table 2 Self-assessment (Skin condition)

Item	Mean				Rate of change			Significant *P* value compared with D0		
	D0	D7	D21	D42	D7	D21	D42	D7	D21	D42
Skin firmness	6.00	4.90	3.55	2.42	-1.10	-2.45	-3.58	<0.001	<0.001	<0.001
Skin gloss	6.13	4.97	3.65	2.35	-1.16	-2.48	-3.77	<0.001	<0.001	<0.001
Skin hyperpigmentation	6.35	5.03	3.77	2.55	-1.32	-2.58	-3.81	<0.001	<0.001	<0.001
Forehead wrinkles	6.26	5.00	3.61	2.45	-1.26	-2.65	-3.81	<0.001	<0.001	<0.001
Crow's feet wrinkles	6.03	4.94	3.61	2.61	-1.10	-2.42	-3.42	<0.001	<0.001	<0.001
Nasolabial folds	6.19	5.00	3.65	2.39	-1.19	-2.55	-3.81	<0.001	<0.001	<0.001
Skin evenness	6.39	5.13	3.61	2.42	-1.26	-2.77	-3.97	<0.001	<0.001	<0.001
Jawline lifting	6.23	5.00	3.52	2.29	-1.23	-2.71	-3.94	<0.001	<0.001	<0.001
Skin hydration	6.00	4.94	3.61	2.48	-1.06	-2.39	-3.52	<0.001	<0.001	<0.001

Grading scale: 0 to 9 score, 0 score means very good; 4-5 score means general; 9 score means very poor.

Compared with before application:

7 days after application, the score of skin firmness decreased by 1.10 significantly, the score of skin gloss decreased by 1.16 significantly, the score of skin hyperpigmentation decreased by 1.32 significantly, the score of forehead wrinkles decreased by 1.26 significantly, the score of crow's feet wrinkles decreased by 1.10 significantly, the score of nasolabial folds decreased by 1.19 significantly, the score of skin evenness decreased by 1.26 significantly, the score of jawline lifting decreased by 1.23 significantly, the score of skin hydration decreased by 1.06 significantly;

21 days after application, the score of skin firmness decreased by 2.45 significantly, the score of skin gloss decreased by 2.48 significantly, the score of skin hyperpigmentation decreased by 2.58 significantly, the score of forehead wrinkles decreased by 2.65 significantly, the score of crow's feet wrinkles decreased by 2.42 significantly, the score of nasolabial folds decreased by 2.55 significantly, the score of skin evenness decreased by 2.77 significantly, the score of jawline lifting decreased by 2.71 significantly, the score of skin hydration decreased by 2.39 significantly.

42 days after application, the score of skin firmness decreased by 3.58 significantly, the score of skin gloss decreased by 3.77 significantly, the score of skin hyperpigmentation decreased by 3.81 significantly, the score of forehead wrinkles decreased by 3.81 significantly, the score of crow's feet wrinkles decreased by 3.42 significantly, the score of nasolabial folds decreased by 3.81 significantly,

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 化妆品及日化产品部 Cosmetics, Personal Care & Household

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

the score of evenness of skin color decreased by 3.97 significantly, the score of jawline lifting decreased by 3.94 significantly, the score of skin hydration content decreased by 3.52 significantly.

Table 3 Result of self-assessment (Satisfaction)

Question	Satisfaction		
	7 days after application	21 days after application	42 days after application
After using, felling the product is mild and non-irritating	90%	100%	97%
After using, felling the skin is more elastic	87%	100%	100%
After using, the skin touches smoother	90%	100%	97%
After using, the product is effective in improving dullness of the skin	87%	100%	97%
After using, feeling the skin is more translucent	84%	100%	97%
After using, the product is effective in firming the skin	90%	100%	100%
After using, the product is effective in minimizing dry fine lines	87%	100%	97%
After using, the product is effective in improving sagging	84%	100%	97%
After using, the product is effective in improving skin roughness	87%	100%	97%
After using, the product is effective in enhancing the skin's gloss	87%	100%	97%
After using, satisfied with product effect/efficacy	87%	100%	97%
After using, willing continue using the product	87%	100%	97%
After using, would recommend the product to friends	90%	100%	97%
After using, thinking the skin is fairer	81%	100%	97%
After using, thinking the skin is more delicate	81%	100%	97%
Easy to use	90%	100%	97%
After using, the product is effective in immediate lifting and firming	87%	100%	97%
After using, the lifting and firming effect lasts all day	87%	100%	97%
The gel used with is easy to apply	87%	100%	97%
The gel used with is easy to clean	90%	100%	97%
After using, the product is effective in improving firmness of jawline	87%	100%	97%

Grading scale: Satisfaction: 1-7 score（1 means highly dissatisfied , 7 means highly satisfied）
Satisfaction = number of subjects who chose more than 4 score ÷ valid data × 100%

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

7 days after application, 90% subjects thought "After using, felling the product is mild and non-irritating", 87% subjects thought "After using, felling the skin is more elastic", 90% subjects thought "After using, the skin touches smoother ", 87% subjects thought "After using, the product is effective in improving dullness of the skin", 84% subjects thought "After using, feeling the skin is more translucent", 90% subjects thought "After using, the product is effective in firming the skin", 87% subjects thought "After using, the product is effective in minimizing dry fine lines", 84% subjects thought "After using, the product is effective in improving sagging", 87% subjects thought "After using, the product is effective in improving skin roughness", 87% subjects thought "After using, the product is effective in enhancing the skin's gloss", 87% subjects thought "After using, satisfied with product effect/efficacy", 87% subjects thought "After using, willing continue using the product", 90% subjects thought "After using, would recommend the product to friends", 81% subjects thought "After using, thinking the skin is fairer", 81% subjects thought "After using, thinking the skin is more delicate ", 90% subjects thought "Easy to use", 87% subjects thought "After using, the product is effective in immediate lifting and firming ", 87% subjects thought "After using, the lifting and firming effect lasts all day ", 87% subjects thought "The gel used with is easy to apply", 90% subjects thought "The gel used with is easy to clean", 87% subjects thought "After using, the product is effective in improving firmness of jawline".

21 days after application, 100% subjects thought "After using, felling the product is mild and non-irritating", 100% subjects thought "After using, felling the skin is more elastic", 100% subjects thought "After using, the skin touches smoother ", 100% subjects thought "After using, the product is effective in improving dullness of the skin", 100% subjects thought "After using, feeling the skin is more translucent", 100% subjects thought "After using, the product is effective in firming the skin", 100% subjects thought "After using, the product is effective in minimizing dry fine lines", 100% subjects thought "After using, the product is effective in improving sagging", 100% subjects thought "After using, the product is effective in improving skin roughness", 100% subjects thought "After using, the product is effective in enhancing the skin's gloss", 100% subjects thought "After using, satisfied with product effect/efficacy", 100% subjects thought "After using, willing continue using the product", 100% subjects thought "After using, would recommend the product to friends", 100% subjects thought "After using, thinking the skin is fairer", 100% subjects thought "After using, thinking the skin is more delicate ", 100% subjects thought "Easy to use", 100% subjects thought "After using, the product is effective in immediate lifting and firming ", 100% subjects thought "After using, the lifting and firming effect lasts all day ", 100% subjects thought "The gel used with is easy to apply", 100% subjects thought "The gel used with is easy to clean", 100% subjects thought "After using, the product is effective in improving firmness of jawline".

42 days after application, 97% subjects thought "After using, felling the product is mild and non-irritating", 100% subjects thought "After using, felling the skin is more elastic", 97% subjects thought "After using, the skin touches smoother ", 97% subjects thought "After using, the product is effective in improving dullness of the skin", 97% subjects thought "After using, feeling the skin is more translucent", 100% subjects thought "After using, the product is effective in firming the skin", 97% subjects thought "After using, the product is effective in minimizing dry fine lines", 97% subjects thought "After using, the product is effective in improving sagging", 97% subjects thought "After using, the product is effective in improving skin roughness", 97% subjects thought "After using, the product is

RAND: **94945210**

浦标标准技术服务有限公司杭州分公司 化妆品及日化产品部 Cosmetics, Personal Care & Household
SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch Cosmetics, Personal Care & Household

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

effective in enhancing the skin's gloss", 97% subjects thought "After using, satisfied with product effect/efficacy", 97% subjects thought "After using, willing continue using the product", 97% subjects thought "After using, would recommend the product to friends", 97% subjects thought "After using, thinking the skin is fairer", 97% subjects thought "After using, thinking the skin is more delicate ", 97% subjects thought "Easy to use", 97% subjects thought "After using, the product is effective in immediate lifting and firming ", 97% subjects thought "After using, the lifting and firming effect lasts all day ", 97% subjects thought "The gel used with is easy to apply", 97% subjects thought "The gel used with is easy to clean", 97% subjects thought "After using, the product is effective in improving firmness of jawline".

5. Conclusion

Compared with before application, 42 days after application, skin tone L* and skin tone ITA° had improved significantly, the test result showed that the test sample had spot-removing and whitening efficacy.

Compared with before application, 7 days after application, 21 days after application, 42 days after application, skin firmness F4, skin elasticity R2, skin elasticity R5 and skin elasticity R7 had improved significantly, the test result showed that the test sample had firmness efficacy.

Compared with before application, 7 days after application, image analysis showed that the on the forehead, average depth of wrinkles, volume of wrinkles, area of wrinkles, length of wrinkles had improved significantly; On the crow's feet, volume of wrinkles, area of wrinkles, length of wrinkles had improved significantly; On nasolabial fold: average depth of skin wrinkles, volume of wrinkles, area of wrinkles, length of wrinkles had improved significantly; 21 days after application, image analysis showed that on the forehead: average depth of wrinkles, volume of wrinkles, area of wrinkles had improved significantly. On the crow's feet, the average depth of wrinkles, volume of wrinkles, area of wrinkles had improved significantly; On the nasolabial fold, volume of wrinkles, area of wrinkles had improved significantly, 42 days after application, image analysis showed that on the forehead: volume of wrinkles, area of wrinkles had improved significantly. On the crow's feet, volume of wrinkles, area of wrinkles had improved significantly; On the nasolabial fold, volume of wrinkles, area of wrinkles, length of wrinkles had improved significantly, the test result showed that the test sample had anti-wrinkle efficacy.

6. Adverse Events

No adverse events (AEs) were recorded during the course of the study.

7. Deviations and revisions to the protocol

This test was carried out in full accordance with the test protocol.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 浙标标准技术服务有限公司杭州分公司 化妆品及日化产品部 Cosmetics, Personal Care & Household

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

8. Sample Photo



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

9. Appendix I: Subject Information

NO.	Name (Initial)	Gender	Age	Fitzpatrick Skin typing	Facial skin type	Facial laxity	Color difference between the isolated hyperpigmentation and the surrounding skin	Forehead wrinkles	Nasolabial fold wrinkles	Crow's feet wrinkles
001	ZGY	Female	55	IV	Combination oily	4.5	3.5	3.5	4	4
003	LL	Female	39	II	Combination oily	4.5	1.5	3.5	3.5	3
004	FYP	Female	51	IV	Dry	4.5	1.5	3.5	4.5	4.5
005	ZYH	Female	40	IV	Combination dry	4.5	3.5	3.5	4	4
006	ZZH	Female	50	IV	Normal	5	3	3.5	4	4
007	DGJ	Female	42	IV	Combination dry	4.5	3	3.5	3.5	3
008	ZXH	Female	50	IV	Combination dry	4	1.5	3	4	4
009	YJL	Female	54	IV	Combination oily	4.5	3	3	4	4
010	LJ	Female	50	III	Dry	5	2.5	3	4.5	3.5
011	CQZ	Female	43	IV	Combination oily	4	1.5	3	3.5	3
012	WCH	Female	52	II	Dry	4	2	3.5	4	3.5
013	QCM	Female	51	III	Combination oily	5	2.5	3.5	6	3.5
014	WLX	Female	52	IV	Dry	4	1.5	3	3.5	3.5
015	QWH	Female	51	IV	Dry	4.5	3	3	4	3.5
016	XJG	Female	47	III	Normal	4	1.5	3	4.5	3
017	XGH	Female	48	III	Dry	4.5	1.5	3	4	3.5
018	LLM	Female	45	III	Combination oily	4.5	2.5	3	3.5	3.5
019	WHX	Female	48	IV	Combination oily	5	2.5	4	5.5	4
020	LJF	Male	40	III	Combination oily	4	3	5	4	4
021	YCX	Female	49	IV	Dry	4.5	2.5	4	4	3.5
022	WXJ	Female	54	III	Dry	4.5	3	4.5	6	4
023	JJ	Female	35	IV	Dry	4.5	3.5	3.5	3.5	3
024	HY	Female	46	IV	Combination dry	4.5	2	3	4	3
025	FDF	Female	46	IV	Combination dry	4	2.5	3.5	3.5	3.5

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

NO.	Name (Initial)	Gender	Age	Fitzpatrick Skin typing	Facial skin type	Facial laxity	Color difference between the isolated hyperpigmentation and the surrounding skin	Forehead wrinkles	Nasolabial fold wrinkles	Crow's feet wrinkles
026	JWF	Female	45	IV	Dry	4	2	2.5	3	3
027	YJ	Female	51	IV	Dry	4.5	3	4	3.5	3.5
028	MRX	Female	41	III	Combination dry	4.5	1.5	3.5	3.5	3
029	LH	Female	51	IV	Dry	4.5	1.5	3.5	4.5	3.5
031	HYH	Female	54	IV	Dry	4.5	2	3.5	4.5	3.5
032	CYQ	Male	51	III	Combination dry	3.5	2.5	3	3	4
034	XYJ	Female	53	III	Combination dry	4.5	2	3.5	3.5	4

Remarks: #02, #30, #33 subjects didn't return to the lab on time and exited the test

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

10. Appendix II: Protocol

Protocol No. HZFF23092602

SGS (Hangzhou) Human Efficacy Assessment

A Study to Assess the Efficacy of ZIIP BEAUTY HALO

Test purpose	This single-center clinical trial is being conducted to assess the rate of improvement in terms of skin elasticity, skin firmness, skin gloss, skin evenness, degree of pigmentation, and degree of wrinkles of the Sponsor' s test sample when used over the course of 42 day by healthy adults.
Before test	The following relevant safety test data and instructions must be provided to the laboratory for evaluation before conducting human tests: Product safety instructions, product-related toxicological test reports, human patch test reports, and signed a commitment to bear the corresponding treatment and expenses for the adverse reactions of the subjects during the efficacy test.
Test product	ZIIP BEAUTY HALO
Test method	Compare with Baseline
Number of subjects	30+3 subjects (at least 30 subjects)
Inclusion Criteria	1. Healthy male or female, 25 to 55 years of age. 2. Race: Asian (Chinese). 3. Self-reported facial complexion is dull, rough and lacks elasticity. 4. The tactile assessment of facial laxity 3-6. 5. Facial hyperpigmentation ≥ 3mm in diameter and the isolated hyperpigmentation has a visual score of 1-4 on the color difference between the hyperpigmentation and the surrounding skin, according to the Skin Aging Atlas (Asian). 6. The forehead wrinkles on a visual scale of 2-6 (according to the SGS standard map). 7. The nasolabial fold on random side of face on a visual scale of 3-6 (according to the SGS standard map). 8. The crow's feet on random side of eyes on a visual scale of 3-6 (according to the SGS standard map). 9. No obvious skin redness, lesions, scars, hair, etc. on the facial skin. 10. Be able to cooperate well with the test according to the requirements of the test plan and maintain the regularity of life during the test period.
Exclusion Criteria	1. Those who do not agree to sign the informed consent form. 2. Those who are unwilling to comply with the program requirements. 3. Currently participating in any other clinical trial at the same time. 4. Use of cosmetic products or/and medicines on the day of the test. 5. Breastfeeding, pregnant, or planning to become pregnant during the study according to subject self-report. 6. Currently receiving drug treatment during the test period. 7. Those who are suffering from infectious skin diseases or atopic dermatitis.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)


	8. Those who with skin abnormalities such as moles and telangiectasia at the test sites. 9. Those who have received skin peeling or skin treatment within 3 months before taking the test. 10. Those who have received immunosuppressive therapy within 3 months before taking the test. 11. Those who have received systemic steroid therapy or phototherapy within 1 month before taking the test. 12. Those who have used topical drugs or/and skin care products, cosmetics with special effects (claiming the effects of spot-removing and whitening, anti-wrinkles, firmness) on the involved parts within 2 weeks before participating in the test. 13. There are obvious marks or other abnormalities in the test area, making it difficult to measure. 14. Those who with severe reactions or allergies to cosmetics, drugs, or general light exposure. 15. Those who are suspected or diagnosed predisposition to seizures during pregnancy. 16. Those who are suspected or diagnosed heart disease. 17. Those who are suffering from cancer/tumor. 18. Those who with pacemakers, implantable defibrillators or other implanted metallic or electronic devices. 19. In addition to the above, when it is deemed inappropriate to conduct the test according to the judgment of Investigator of the test.
Product use area	Face
Product Usage Instructions	Step 1: Charging When the instrument needs to be charged, the light band around the center of the instrument will flash orange. To charge, plug the charger into the USB power adapter (not supplied with this product) and then plug the other end into the terminal port of the HALO instrument. The light band will show orange color when charging. It takes 4 hours to fully charge the instrument. When charging is complete, the orange light band will turn off. WARNING: Do not attempt to use the instrument while charging. The product must be charged with an adapter that complies with the GB4706.1-2005 standard and has an output power of less than 15W. Step 2: Skin Preparation Before use, make sure your skin is dry, clean and free of any skincare products such as moisturizers, serums or lotions. Ensure that you are not wearing any jewelry in the area where the device is used or on your hands.

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

	If you have used an oil-based cleanser, make sure there is no residue on your skin as this can cause HALO not to work. Those with facial hair should shave their face before use. Hair can interfere with the electrical conductivity of the spheres, causing the device to not work. Step 3: Apply the gel, hold down the switch and start using it according to the video's technique. At the end of use, use it again, if the gel is not enough you need to replenish the gel. Stop after two times consecutive uses. Wipe off any remaining gel on the skin. Toner or moisturizer can be used immediately as needed. Ensure the device is clean and dry before storing. The use cycle is continuous two days, one day of rest, and two days of use. Use the 4-minute mode twice a day in a row for a total of 8 minutes.
Test area	**Face**  ● Glossymeter measurement area: Highest point of cheekbones (Random side) ● Cutometer measurement area: The intersection of the outer corner of the eye and the corners of the mouth (opposite to Glossymeter measurement side)
Test time points	**42 days** **(D0 (Baseline), D0_Timm (Immediately after using the product), D7 (7 days after application), D21 (21 days after application), D42 (42 days after application)**
Test considerations	1. From two weeks before and during the test, subjects should not use therapeutic agents, cosmetics, external medicines, and health care products that may affect the test effect and aim to improve the skin, and are prohibited from medical treatment, massage, Beauty salon care, etc. 2. Before the start of the test on each return visit day, the subjects clean their face and rest in a constant temperature and humidity room to ensure that the skin remains in a stable state for 30 minutes before the test. 3. **On the day of the test, subjects should stop using facial mask products, during the test period, they must keep their usual skin care products and skin care habits unchanged, and the test samples should replace their original self-use**

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

	skin care products, and other self-use skin care products cannot claim the efficacy of spot-removing and whitening, anti-wrinkles, firmness. 4. During the test, reduce the strong outdoor activities of the sun, and prohibit travel and vacation.
Test items	**1 Environmental conditions** 1.1 Resting waiting area: At a constant temperature of 21±2°C and a relative humidity of 50±10% RH, each subject should be allowed to relax and achieve equilibrium. 1.2 The conditions in the testing area are the same as in the rest waiting area. **2 Instrument measurement** 2.1 Digital Image Capture Instrument: VISIA-CR Area: left, centre and right views Light: Standard 1 (S1), Standard 2 (S2), Polarized(CP) Test time: D0(Baseline), D7, D21, D42 2.2 Image Analysis – Color analysis Image: VISIA-CP & IPP Analysis-CP image Area: random side of cheek Parameters: L*, ITA° Test time: D0(Baseline), D7, D21, D42 2.3 Image Analysis - Evenness analysis Image: VISIA-CP & IPP Analysis-CP image Area: random side of cheek Parameters: Intensity-SD Test time: D0(Baseline), D7, D21, D42 2.4 Three-dimensional imaging capture Instrument: Primos CR Area: forehead, random side of outer corners of the eye, random side of nasolabial fold Test time: D0(Baseline), D7, D21, D42 2.5 Image analysis – Wrinkle analysis Instrument: Primos CR Area: forehead, random side of outer corners of the eye, random side of nasolabial fold Parameter: number, volume, area, length, depth Test time: D0(Baseline), D7, D21, D42

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

2.6 Skin gloss
Instrument: Glossymeter
Parameter: skin gloss value
Area: random side of cheek
Test time: D0(Baseline), D7, D21, D42

2.7 Skin elasticity
Instrument: Cutometer
Parameter: R2, R5, R7
Area: random side of cheek
Test time: D0(Baseline), D7, D21, D42

2.8 Skin firmness
Instrument: Cutometer
Parameter: F4
Area: random side of cheek
Test time: D0(Baseline), D7, D21, D42

3 Subjective assessment

3.1 Dermatologist assessment—Facial skin gloss
Test item: Dermatologist score the skin status of the subjects
Grading scale: 0-9 score (SGS standard grading scale)
Area: global face
Parameter: Grade score
Test time: D0(Baseline), D7, D21, D42

3.2 Dermatologist assessment—Facial skin evenness
Test item: Dermatologist score the skin status of the subjects
Grading scale: 0-9 score (SGS standard grading scale)
Area: global face
Parameter: Grade score
Test time: D0(Baseline), D7, D21, D42

3.3 Dermatologist assessment—Forehead wrinkles
Test item: Dermatologist score the skin status of the subjects
Grading scale: 0-9 score (SGS standard grading scale)
Area: forehead
Parameter: Grade score
Test time: D0(Baseline), D7, D21, D42

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

	3.4 Dermatologist assessment—Nasolabial fold wrinkles Test item: Dermatologist score the skin status of the subjects Grading scale: 0-9 score (SGS standard grading scale) Area: nasolabial Parameter: Grade score Test time: D0(Baseline), D7, D21, D42 3.5 Dermatologist assessment—Crow' s feet wrinkles Test item: Dermatologist score the skin status of the subjects Grading scale: 0-9 score (SGS standard grading scale) Area: outer corner of the eye Parameter: Grade score Test time: D0(Baseline), D7, D21, D42 3.6 Dermatologist assessment- Color difference between the isolated hyperpigmentation and the surrounding skin Test item: Dermatologist score the skin status of the subjects Grading scale: 0-5 score (*Skin Aging Atlas (Asian)*) Area: single brown spot Parameter: Grade score Test time: D0(Baseline), D7, D21, D42 3.7 Subject self-assessment (0-9 score) Test item: Subject's assessment of their own skin condition Grading scale: 0-9 score (0 means very good, 9 means very bad) Area: global face Parameter: Grade score Test time: D0(Baseline), D7, D21, D42 3.8 Subject self-assessment (1-7 score) Test item: Subject's assessment of efficacy and satisfaction with the test sample Grading scale: 1-7 score (1 means highly dissatisfied , 7 means highly satisfied) Area: global face Parameter: Grade score Test time: D0(Baseline), D7, D21, D42
Test items	**Before test**

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

1. The technician should screen qualified subjects who meet the inclusion criteria according to the test requirements and record the Fitzpatrick type and skin type of the subjects' face (dry, oily, combine to dry or combine to oil).

Baseline(D0)

1、After the subjects arrive at SGS, they use facial cleanser provided by the laboratory to clean the face, dry the skin with a lint free dry paper tissue, and sit quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.
2. The dermatologist conducts the assessment.
3. The technician captures facial VISIA CR images, Primos CR images for qualified subjects and conducts the Cutometer measurement and Glossymeter measurement.
4. The subjects fill in the self-assessment questionnaire.
5. The technician explains the product instructions to the subjects and distributes the test samples and the subjects in the laboratory under the supervision of the technician on-site trial evaluation of the product. If there are adverse reactions, they need to fill in the use log in time.

D0_Timm (Immediately after using the product)

1. Subjects use facial cleanser provided by the laboratory to clean the face, dry the skin with a lint free dry paper tissue, and sit quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.
2. The technician conducts the Cutometer measurement.
3. Subjects leave SGS.

7 days after application (D7)

1. After the subjects arrive at SGS, they use facial cleanser provided by the laboratory to clean the face, dry the skin with a lint free dry paper tissue, and sit quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.
2. The dermatologist conducts the assessment.
3. The technician captures facial VISIA CR images, Primos CR images for qualified subjects and conducts the Cutometer measurement and Glossymeter measurement.
4. The subjects fill in the self-assessment questionnaire.
5. The technician weighs the test samples and checks the product usage log.
6. Subjects leave SGS.

21 days after application (D21)

1、After the subjects arrive at SGS, they use facial cleanser provided by the laboratory to clean the face, dry the skin with a lint free dry paper tissue, and sit quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH.

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

	2、The dermatologist conducts the assessment. 3、The technician captures facial VISIA CR images, Primos CR images for qualified subjects and conducts the Cutometer measurement and Glossymeter measurement. 4、The subjects fill in the self-assessment questionnaire. 5、The technician recycles the test samples and the product usage log. 6、Subjects leave SGS. **42 days after application (D42)** 1. After the subjects arrive at SGS, they use facial cleanser provided by the laboratory to clean the face, dry the skin with a lint free dry paper tissue, and sit quietly for 30 minutes in the clinic at a temperature of 21±2 ℃ and 50±10% RH. 2. The dermatologist conducts the assessment. 3. The technician captures facial VISIA CR images, Primos CR images for qualified subjects and conducts the Cutometer measurement and Glossymeter measurement. 4. The subjects fill in the self-assessment questionnaire. 5. The technician recycles the test samples and the product usage log. 6. Subjects leave SGS. Test end
Test report	SPSS 28.0 is used for data statistics, and the test data are tested for normal distribution. If the test data are normally distributed, the T-test method is used for statistical analysis; if the test data are non-normal distribution, the rank sum test method is used for statistical analysis. The rank data is statistically analyzed by the rank sum test. Statistical methods significance level $p<0.05$. Analyze whether there is a significant difference in the values of each test parameter of the test sample compare with Baseline at each time point, and calculate the effective number of people, and issue a report. Statistical Analysis Plan I

Test items	Compare with Baseline	Notes/Interpretation
The analysis parameters of VISIA-CP & IPP Analysis-CP Color analysis (L*, ITA°)	Paired T-test or Wilcoxon signed-rank test	Larger L* values indicate brighter skin color. Larger ITA° values indicate whiter skin color.
The analysis parameters of VISIA CR&IPP Analysis-CP Evenness analysis Intensity-SD	Paired T-test or Wilcoxon signed-rank test	A decreased value indicates an improvement.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

	The analysis parameters of Primos CR images: (number, depth, length, area, volume)	Paired T-test or Wilcoxon signed-rank test	A decreased value indicates an improvement.
	Glossymeter measurement	Paired T-test or Wilcoxon signed-rank test	An increased value indicates an improvement.
	Cutometer measurement (R2, R5, R7, F4)	Paired T-test or Wilcoxon signed-rank test	An increased value of R2, R5, R7 indicates an improvement. A decreased value of F4 indicates an improvement.
	Dermatologist assessment (gloss, evenness, color difference between isolated pigmentation and surrounding skin, forehead wrinkles, nasolabial fold, crow's feet lines)	Wilcoxon signed rank	A decreased value indicates an improvement.
	Subject self-assessment (0-9 score)	Wilcoxon signed rank	A decreased value indicates an improvement.
	Subject self-assessment (1-7 score)	/	Satisfaction is calculated as the percentage of people with > 3 score to the total number of people.
	一、The final report provides images of the 3 subjects before and after use 1.VISIA CR: left, center and right views (after coding) ● S1 ● S2 ● CP 2. Primos CR: forehead, Random side of nasolabial fold, Random side of the outer corner of the eye ● Original images ● Rainbow images ● Filter images		
Project instruction	1. The following relevant safety test data and instructions must be provided for evaluation before conducting human tests, such as product safety instructions, and		

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

	sign a commitment to bear the corresponding treatment and expenses for the adverse reactions of the subjects during the test. 2. The experimental results and reports are explained based on the test samples, experimental schemes, and data. 3. Without the consent of the inspection agency, the sponsor shall not use the test results and the name of the testing agency for any improper publicity and shall not copy (except full text copy) the test report or certificate without written approval.

RAND: **94945210**







Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

11. Appendix III: Image capture of part of subjects

- **VISIA CR: Standard lighting 1**

NO.		Before application	7 days after application	21 days after application	42 days after application
11	Front				
	Left				
	Right				

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch
7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)


NO.		Before application	7 days after application	21 days after application	42 days after application
15	Front				
	Left				
	Right				

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

NO.		Before application	7 days after application	21 days after application	42 days after application
28	Front				
	Left				
	Right				










RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)


- **VISIA CR: Standard lighting 2**

NO.		Before application	7 days after application	21 days after application	42 days after application
11	Front				
	Left				
	Right				

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)





NO.		Before application	7 days after application	21 days after application	42 days after application
15	Front				
	Left				
	Right				

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

NO.		Before application	7 days after application	21 days after application	42 days after application
28	Front				
	Left				
	Right				













RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com




Member of the SGS Group (SGS SA)

- **VISIA CR: Cross-Polarized**

NO.		Before application	7 days after application	21 days after application	42 days after application
11	Front				
	Left				
	Right				

RAND: **94945210**






Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

NO.		Before application	7 days after application	21 days after application	42 days after application
15	Front				
	Left				
	Right				

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

NO.		Before application	7 days after application	21 days after application	42 days after application
28	Front				
	Left				
	Right				









RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Original images (Forehead)**

NO.	Before application	7 days after application	21 days after application	42 days after application
14				
20				
25				








Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch 通标标准技术服务有限公司杭州分公司 化妆品及日化产品部 Cosmetics, Personal Care & Household

7th Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Original images (Crow's feet)**






NO.	Before application	7 days after application	21 days after application	42 days after application
06				
23				
28				

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Original images (Nasolabial fold)**














NO.	Before application	7 days after application	21 days after application	42 days after application
12				
14				
21				

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Filter images (Forehead)**

NO.	Before application	7 days after application	21 days after application	42 days after application	
14					
20					
25					














Bright colors means raised area, dark color means recessed area.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Filter images (Crow's feet)**














NO.	Before application	7 days after application	21 days after application	42 days after application	
06					
23					
28					
Bright colors means raised area, dark color means recessed area.					

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Filter images (Nasolabial fold)**

NO.	Before application	7 days after application	21 days after application	42 days after application	
12					
14					
21					













Bright colors means raised area, dark color means recessed area.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国・浙江・杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Rainbow images (Forehead)**

NO.	Before application	7 days after application	21 days after application	42 days after application	
14					
20					
25					

Blue means raised area, red means recessed area.













RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

- **Primos CR：Rainbow images (Crow's feet)**













NO.	Before application	7 days after application	21 days after application	42 days after application	
06					
23					
28					

Blue means raised area, red means recessed area.

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

- **Primos CR：Rainbow images (Nasolabial fold)**

NO.	Before application	7 days after application	21 days after application	42 days after application	
12					
14					
21					
Blue means raised area, red means recessed area.					

*** End of Report***

RAND: **94945210**

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

7" Building, No.1180 Bin'an Road, Binjiang District, Hangzhou, Zhejiang Province, China 310052 t (86-571) 8717 6125 f (86-571) 8679 1605 www.sgsgroup.com.cn
中国·浙江·杭州市滨江区滨安路1180号7号楼 邮编：310052 t (86-571) 8717 6125 f (86-571) 8679 1605 sgs.china@sgs.com

Member of the SGS Group (SGS SA)